

Specifications

Model	Line Voltage (VAC)	Motor Voltage Range (VDC)	Continuous Motor Current (Amps)	Horsepower Range
PML703-5	115	0 - 140	5.0*	1/20 - 3/4
	or 230	0 - 280		

* When mounted vertically. De-rate to 4.0 amps when mounted horizontally.


AC Line Voltage.....	115/230 VAC ± 10%, 50/60 Hz, single phase
Form Factor.....	1.05
Acceleration Time Range for 0-4000 RPM on a 6-pole motor.....	0.5 - 12 seconds
Deceleration Time Range for 0-4000 RPM on a 6-pole motor.....	0.5 - 12 seconds
Analog Input Voltage Range (S1 to S2).....	0 - 5; 0 to ± 10 VDC
Current Range (S1 to S2).....	4 - 20 mA
Input Impedance (S1 to S2).....	>50K ohms
Load Regulation.....	1% base speed or better
Speed Range.....	100:1
Vibration (0 - 50 Hz).....	0.5G maximum
(>50 Hz).....	0.1G maximum
Ambient Temperature Range.....	0°C - 40°C
Hall Effect Sensors.....	120°, 5 VDC, 75 mA
Weight.....	2.5 lbs

Safety Warnings

READ ALL SAFETY WARNINGS BEFORE INSTALLING THIS EQUIPMENT

- **DO NOT INSTALL, REMOVE, OR REWIRE THIS EQUIPMENT WITH POWER APPLIED.** Have a qualified electrical technician install, adjust and service this equipment. Follow the National Electrical Code and all other applicable electrical and safety codes, including the provisions of the Occupational Safety and Health Act (OSHA), when installing equipment.
- **Circuit potentials are at 115 or 230 VAC above earth ground.** Avoid direct contact with the printed circuit board or with circuit elements to prevent the risk of serious injury or fatality. Use a non-metallic screwdriver for adjusting the calibration trim pots. Use approved personal protection equipment and insulated tools if working on this drive with power applied.
- Reduce the chance of an electrical fire, shock, or explosion by using proper grounding techniques, over-current protection, thermal protection, and enclosure. Follow sound maintenance procedures.
- **ACE strongly recommends the installation of a master power switch in the line voltage input.** The switch contacts should be rated for 250 VAC and 200% of motor nameplate current.
- **Removing AC line power is the only acceptable method for emergency stopping.** Do not use regenerative braking, decelerating to minimum speed, or coasting to a stop for emergency stopping. They may not stop a drive that is malfunctioning. Removing AC line power is the only acceptable method for emergency stopping.
- Line starting and stopping (applying and removing AC line voltage) is recommended for infrequent starting and stopping of a drive only. Regenerative braking, decelerating to minimum speed, or coasting to a stop is recommended for frequent starts and stops. Frequent starting and stopping can produce high torque. This may cause damage to motors.
- **Do not disconnect any of the motor leads from the drive** unless power is removed or the drive is disabled. Opening any one lead while the drive is running may destroy the drive.
- Under no circumstances should power and logic level wires be bundled together.
- Be sure potentiometer tabs do not make contact with the potentiometer's body. Grounding the input will cause damage to the drive.
- **Only connect to terminal L2-DBL if using a 115 VAC line with a motor rated higher than 130 VDC.**

Dimensions



Installation

Mounting

- Drive components are sensitive to electrostatic discharge. Avoid direct contact with the circuit board. Hold the drive by the plate only.
- Protect the drive from dirt, moisture, and accidental contact.
- Provide sufficient room for access to the terminals and calibration trim pots.
- Mount the drive away from heat sources. Operate the drive within the specified ambient operating temperature range.
- Prevent loose connections by avoiding excessive vibration of the drive.
- Mount the drive with its board in either a horizontal or vertical plane. Four 0.17" (4 mm) holes in the heat sink accept #8 pan head screws. If mounted horizontally, the drive must be de-rated to 5.5 amps.
- The heat sink should be earth grounded.

Wiring

Use 18 - 24 AWG wire for logic wiring. Use 14 - 16 AWG wire for AC line and motor wiring.

Shielding Guidelines

As a general rule, ACE recommends shielding of all conductors. If it is not practical to shield power conductors, ACE recommends shielding all logic-level leads. If shielding of logic-level leads is not practical, the user should twist all logic leads with themselves to minimize induced noise. It may be necessary to earth ground the shielded cable. If noise is produced by devices other than the drive, ground the shield at the drive end. If noise is generated by the drive, ground the shield at the end away from the drive. Do not ground both ends of the shield.

Fusing


ACE drives require an external line fuse for protection. Use fast acting fuses rated for 250 VAC or higher and 150% of the maximum armature current. Fuse the HOT leg of the AC line when using 115 VAC and both lines when using 230 VAC.

Line Input

If using a 115 VAC line with a 130 VDC motor or a 230 VAC line with a 130/260 VDC motor, connect to terminals L1 and L2. If using a 115 VAC line with a 260 VDC motor, connect to terminals L1 and L2-DBL. Minarik Drives recommends the use of a double-pole, single-throw master power switch. The switch should be rated at a minimum of 250 VAC and 200% of motor current.

Motor

Connect the motor leads to terminals U/A2, V/A1, and W.



Connections

POWER (BOTTOM BOARD)

LOGIC (TOP BOARD)

Speed Potentiometer

Use a 10K ohm, 1/4 W potentiometer for speed control. Connect the counter-clockwise end of the potentiometer to S1, wiper to S2, and the clockwise end to S3. If the potentiometer works inversely of desired functionality, (i.e. to increase motor speed, you must turn the potentiometer counterclockwise), power off the drive and swap the S1 and S3 connections.

Analog Input Signal Range

Instead of using a speed adjust potentiometer, PML series drives may be wired to follow an analog input signal. This input signal can be in the form of voltage (0-5, 0 to ±10 VDC) or current (4-20 mA). Because these drives have built in isolation, the input signal can be grounded or ungrounded (floating). Connect the signal common (-) to S1 and the signal reference (+) to S2. See the Operations section for jumper settings.

Enable


Short terminals EN and COM to accelerate the motor to set speed. Open the ENABLE terminals to coast the motor to zero speed. If no ENABLE switch is desired, wire a jumper between terminals COM and EN. **Do not use the enable for emergency stopping.**

Direction

Short terminals DIR and COM to change the direction of the motor. If no direction switch is desired, leave this connection open.

Hall Effect Sensors

Connect your hall effect sensor common to terminal COM. If the hall effects can be powered by a +5V source, connect the source to terminal +5V. If the hall effect sensors require a source other than +5V, a separate power source must be used to power the hall effects (the COM connection must be made to the hall effect sensors and the separate power supply). Connect your sensors to terminals HALL A, HALL B, and HALL C. The specific connections will vary with each motor (ABC ACB BAC BCA CAB CBA).



Startup

SELECT SWITCHES

Select Switch (SW501)

- Dip Switch 1: ON - Inverted Sensors - The motor's hall effect sensors are inverted.
 OFF - Noninverted Sensors - The motor's hall effect sensors are not inverted.

If at anytime during the wiring setup and trying different hall effect combinations the motor runs away in the reverse direction, disable the drive and toggle dip switch 1.

- Dip Switch 2: ON - High MAX SPEED - Sets a higher maximum speed on the MAX SPEED trim pot.
 OFF - Low MAX SPEED - Sets a lower maximum speed on the MAX SPEED trim pot.

If during calibration, turning the MAX SPEED trim pot fully down (fully CCW) is still to high of a max speed, then set dip switch 2 to OFF.

- Dip Switch 3: ON - WigWag Mode - The potentiometer or analog signal determines both motor speed and direction. The direction switch will still come into effect.

	Full Speed Reverse	Zero Speed	Full Speed Forward
Potentiometer	Full CCW	12 o'clock	Full CW
0 - 5 VDC	0 VDC	2.5 VDC	5 VDC
0 - 10 VDC	0 VDC	5 VDC	10 VDC
4 - 20 mA	4 mA	12 mA	20 mA

- OFF - Pot/Switch Mode - The potentiometer or analog signal (0 - 5 VDC, 0 - 10 VDC, 4-20 mA) determines the motor speed while the direction switch determines the direction. If using a bidirectional analog signal (0 to ± 10 VDC), the polarity of the signal determines the direction (ie -10 VDC is full speed reverse, 0 VDC is zero speed, 10 VDC is full speed forward). The direction switch will still come into effect even with a bidirectional signal.

- Dip Switch 4: ON - Brake Mode - Opening the ENABLE switch will regeneratively brake the motor to zero speed without applying the decel ramp. At zero speed, the drive will apply holding torque.
 OFF - Enable Mode - Opening the ENABLE switch will coast the motor to a stop. The drive cannot provide holding torque at zero speed because it's disabled.

JUMPERS



0-5 VDC or Potentiometer
 Jumper Pins 1&2 and 7&8



0 to ± 10 VDC
 Jumper Pins 3&5 and 7&8



4-20 mA
 Jumper Pins 5&6 and 9&10

STARTUP

- Verify that no foreign conductive material is present on the printed circuit board.
- Ensure that all switches and jumpers are properly set.

1. Turn the speed adjust potentiometer full counterclockwise (CCW) or set the analog input voltage or current signal to minimum.
2. Apply AC line voltage.
3. Close the enable switch and verify that the green Power LED (IL1) is flashing.
4. Slowly advance the speed adjust potentiometer clockwise (CW) or increase the analog input voltage or current signal. The motor slowly accelerates as the potentiometer is turned CW or as the analog input voltage or current signal is increased. Continue until the desired speed is reached.
5. Remove AC line voltage from the drive to coast the motor to a stop.

Calibration

CALIBRATION INSTRUCTIONS ARE ASSUMING THAT THE DRIVE IS SET UP FOR POT/SWITCH MODE. IF USING WIGWAG MODE, PLEASE REFER TO THE USER'S MANUAL.

Zero Adjust (P1 / ZERO ADJ): The ZERO ADJ setting adjusts out any non-linearities in the logic circuit that might arise from component tolerances. This is factory calibrated and should not need any adjustment.

Minimum Speed (P2 / MIN SPEED): The MIN SPEED setting determines the minimum motor speed when the speed adjust potentiometer is set for minimum speed. It is factory set for zero speed. To calibrate the MIN SPEED:

1. Set the MIN SPEED trim pot full CCW.
2. Set the speed adjust potentiometer or input voltage or current signal for minimum speed.
3. Adjust the MIN SPEED trim pot until the desired minimum speed is reached or is just at the threshold of rotation.

Maximum Speed (P3 / MAX SPEED): The MAX SPEED setting determines the maximum motor speed when the speed adjust potentiometer or input voltage or current signal is set for maximum speed. It is factory set for maximum motor rated speed. To calibrate the MAX SPEED:

1. Set the MAX SPEED trim pot full CCW.
2. Set the speed adjust potentiometer or input voltage or current signal for maximum forward speed.
3. Adjust the MAX SPEED trim pot until the desired maximum forward speed is reached.

Check the ZERO ADJ, MIN SPEED, and MAX SPEED adjustments after recalibrating to verify that the motor runs at the desired minimum and maximum speeds.

Acceleration (P4 / ACCEL TIME): The ACCEL TIME setting determines the time the motor takes to ramp to a higher speed regardless of direction. To calibrate the ACCEL TIME, turn the ACCEL TIME trim pot CW to increase the forward acceleration time and CCW to decrease the forward acceleration time.

Deceleration (P5 / DECEL TIME): The DECEL TIME setting determines the time the motor takes to ramp to a lower speed regardless of direction. To calibrate the DECEL TIME, turn the DECEL TIME trim pot CW to increase the forward deceleration time and CCW to decrease the forward deceleration time.

Forward Torque (P6 / MOTOR CUR LIM): The MOTOR CUR LIM setting determines the maximum torque for accelerating and driving the motor in the forward or reverse directions. To calibrate the MOTOR CUR LIM:

1. With the power disconnected from the drive, connect a DC ammeter in series with one of the motor phases.
2. Set both the MOTOR CUR LIM trim pot to minimum and speed adjust potentiometer to minimum (full CCW). If using an input voltage or current signal, set it to minimum.
3. Carefully lock the rotor shaft. Be sure that the motor is firmly mounted.
4. Apply power source. The motor should be stopped.
5. Slowly advance the speed adjust potentiometer clockwise or slowly increase the input voltage or current signal.
If no current is seen on the DC ammeter, then either;
 - Remove power and connect the ammeter in series with another phase until a current is read.
 - Remove the lock on the shaft and allow it to turn until a current is read.
If the current read is negative, and your meter can only handle positive current, then either;
 - Remove power and swap the ammeter leads.
 - Toggle the state of the Direction Switch.
 Once current can be read, set the speed adjust potentiometer for maximum (full CW) or increase the input voltage or current signal to maximum.
6. Slowly adjust the MOTOR CUR LIM trim pot CW until the current is 150% of motor rated current.
7. Turn the speed adjust potentiometer to minimum speed (full CCW) or set the input voltage or current signal to minimum.
8. Remove power source.
9. Remove the stall from the motor.
10. Remove the ammeter in series with the motor phase if it is no longer needed.

Reverse Torque (P7 / REGEN CUR LIM): The REGEN CUR LIM setting determines the maximum torque for decelerating the motor and resisting an overhauling load in the forward and reverse directions. Turn the REGEN CUR LIM trim pot CW to increase the regen current limit and CCW to decrease the regen current limit.

Proportional Gain (P8 / Kp): The constant used to scale the error feedback. It's used to determine the amount of error in the set speed vs. commanded speed. The lower the Kp, the more the motor speed will drop under a load increase. However, if Kp is too high, it will cause the motor rotation to be rough. To calibrate the Kp:

1. Turn Kp and Ki to minimum (full CCW).
2. With the motor running, turn the Kp trim pot up (CW) until the motor rotation starts to become rough. Slightly turn the Kp trim pot down (CCW) until motor rotation is smooth again.


Integral Gain (P9 / Ki): The constant used to scale the sum of errors over time. The lower the Ki, the longer it will take motor to return to commanded speed after a load change. If the Ki is too high, it will cause oscillation. Calibrate the Ki after calibrating Kp.

LEDs

Power (IL1): Green LED is solid when AC line voltage is applied to the drive, but the drive is disabled. It flashes whenever AC line voltage is applied to the drive and the drive is enabled.

Status (IL2): Red LED is solid when in current limit or flashes following fault code:

- 2 Flashes: Undervoltage - Internal DC BUS voltage dropped below 91 VDC. Will automatically clear when the DC BUS voltage rises to at least 99.5 VDC.
- 3 Flashes: Overvoltage - Internal DC BUS voltage rose above 430 VDC. Will automatically clear when the DC BUS voltage drops to at least 409 VDC.
- 4 Flashes: Current Limit or Short Circuit - The drive is in current limit or has detected a short across at least two phases.
- 5 Flashes: Overtemperature Shut Down - Drive's temperature has reached critical temperature.
- 6 Flashes: Overtemperature Warning - Drive's temperature is approaching critical temperature. Maximum motor current is being reduced gradually as the drive's temperature rises.



Operation

DECLERATING & STOPPING

Decelerate to Minimum or Zero Speed

The switch shown below may be used to decelerate a motor to a minimum speed. Opening the switch between S3 and the potentiometer decelerates the motor from set speed to a minimum speed determined by the MIN SPEED trim pot setting. If the MIN SPEED trim pot is set full CCW, the motor decelerates to zero speed when the switch is opened. The DECEL TIME trim pot setting determines the rate at which the drive decelerates when traveling in the forward direction. By opening the switch, the motor accelerates to set speed at a rate determined by the ACCEL TIME trim pot setting if accelerating in the forward direction.

