

Specifications

Model	Line Voltage (VAC)	Armature Voltage Range (VDC)	Continuous Armature Current (Amps)	Armature Horsepower Range
RGM403-3	115	0 - 90	3.0	1/20 - 1/8
	230	0 - 180		1/10 - 1/4
RGM403-10	115	0 - 90	10.0*	1/4 - 1
	230	0 - 180		1/2 - 2

* Heat sink kit (part number HSK-0004) must be used when the output is over 7 amps.


AC Line Voltage.....	115/230 VAC ± 10%, 50/60 Hz, single phase
Form Factor.....	1.37 at base speed
Field Voltage with 115 VAC line voltage.....	50 or 100 VDC
with 230 VAC line voltage.....	100 or 200 VDC
Maximum Field Current.....	1 Amp
Acceleration Time Range.....	0.5 - 15 seconds
Deceleration Time Range.....	0.5 - 15 seconds
Analog Input Voltage Range.....	0 to ± 25, 0 to ± 250 VDC
Current Range.....	1 - 5, 4 - 20, 10 - 50 mA
Input Impedance Voltage Signal.....	>25k ohms
Current Signal (1-5 mA).....	1K ohms
Current Signal (4-20 mA).....	235 ohms
Current Signal (10-50 mA).....	100 ohms
Load Regulation with Armature Feedback.....	1% base speed
with Tachogenerator Feedback.....	0.1% base speed
Speed Range with Armature Feedback.....	50:1
with Tachogenerator Feedback.....	60:1
Vibration (0 - 50 Hz).....	0.5G maximum
(>50 Hz).....	0.1G maximum
Ambient Temperature Range.....	10°C - 55°C
Weight.....	2.1 lbs
Safety Certifications.....	UL/cUL Listed Equipment, file # E132235

Safety Warnings

READ ALL SAFETY WARNINGS BEFORE INSTALLING THIS EQUIPMENT

- **DO NOT INSTALL, REMOVE, OR REWIRE THIS EQUIPMENT WITH POWER APPLIED.** Have a qualified electrical technician install, adjust and service this equipment. Follow the National Electrical Code and all other applicable electrical and safety codes, including the provisions of the Occupational Safety and Health Act (OSHA), when installing equipment.
- **Circuit potentials are at 115 or 230 VAC above earth ground.** Avoid direct contact with the printed circuit board or with circuit elements to prevent the risk of serious injury or fatality. Use a non-metallic screwdriver for adjusting the calibration trim pots. Use approved personal protection equipment and insulated tools if working on this drive with power applied.
- Reduce the chance of an electrical fire, shock, or explosion by using proper grounding techniques, over-current protection, thermal protection, and enclosure. Follow sound maintenance procedures.
- **ACE strongly recommends the installation of a master power switch in the line voltage input.** The switch contacts should be rated for 250 VAC and 200% of motor nameplate current.
- **Removing AC line power is the only acceptable method for emergency stopping.** Do not use regenerative braking, decelerating to minimum speed, or coasting to a stop for emergency stopping. They may not stop a drive that is malfunctioning. Removing AC line power is the only acceptable method for emergency stopping.
- Line starting and stopping (applying and removing AC line voltage) is recommended for infrequent starting and stopping of a drive only. Regenerative braking, decelerating to minimum speed, or coasting to a stop is recommended for frequent starts and stops. Frequent starting and stopping can produce high torque. This may cause damage to motors.
- **Do not disconnect any of the motor leads from the drive** unless power is removed or the drive is disabled. Opening any one lead while the drive is running may destroy the drive.
- The field output is for shunt wound motors only. Do not make any connections to F1 and F2 when using a permanent magnet motor.
- Change voltage switch settings only when the drive is disconnected from AC line voltage. Make sure both switches are set to their correct position. If the switches are improperly set to a lower voltage position, the motor will not run at full voltage and may cause damage to the transformer. If the switches are improperly set to a higher voltage, the motor will overspeed, which may cause motor damage, or result in bodily injury or loss of life.
- Under no circumstances should power and logic level wires be bundled together.
- Be sure potentiometer tabs do not make contact with the potentiometer's body. Grounding the input will cause damage to the drive.

Dimensions



ALL DIMENSIONS IN INCHES [MILLIMETERS]

Connections

POWER

Line Input

Connect the AC line power leads to terminals L1 and L2, or to a double-pole, single-throw master power switch (recommended). The switch should be rated at a minimum of 250 VAC and 200% of motor current.

Motor

Connect the DC armature leads to terminals A1 and A2. If the motor does not spin in the desired direction, power down the drive and reverse these connections.

Field

At 115 VAC, connect the field leads to terminals F1 and L1 for a 50 VDC field or to F1 and F2 for a 100 VDC field. At 230 VAC, connect the field leads to terminals F1 and L1 for a 100 VDC field or to F1 and 2 for a 200 VDC field. **Do not make any connections to F1 and F2 if using a permanent magnet motor.**

Speed Potentiometer

Use a 10K ohm, 1/4 W potentiometer for speed control. Connect the counter-clockwise end of the potentiometer to terminal 7 (COM), wiper to terminal 8 (INPUT 1), and the clockwise end to terminal 6 (+15). If the potentiometer works inversely of desired functionality, (i.e. to increase motor speed, you must turn the potentiometer counterclockwise), power off the drive and swap terminals 7 (COM) and 6 (+15). See the Operation section for alternative wiring setups.

Analog Input Signal Range

Instead of using a speed adjust potentiometer, RGA403 series drives may be wired to follow an analog input signal. This input signal can be in the form of voltage (0 ± 250 VDC) or current (1 - 5, 4 - 20, 10 - 50 mA). Because these drives have built in isolation, the input signal can be grounded or ungrounded (floating). Connect the analog common to terminal 7 (COM). If using an analog current signal or a voltage range smaller than 0 ± 25 VDC, connect the analog reference to terminal 8 (INPUT 1). If using a voltage range larger than 0 ± 25 VDC, connect the analog reference to terminal 9 (INPUT 2).

Direction

Short terminals DIR and +5V to change the direction of the motor. If no direction switch is desired, leave this connection open.

LOGIC (BOTTOM BOARD)

Inhibit

Short the INHIBIT terminals to regeneratively brake the motor to zero speed. The INHIBIT terminals bypass the FWD ACC and REV ACC trim pots. Open the INHIBIT terminals to accelerate the motor to set speed. ACE offers two accessory plug harnesses for connecting to the inhibit terminals; part number KTW-0001 [18 in (46 cm) leads] and part number KTW-0002 [36 in (91 cm) leads]. **Do not use the inhibit for emergency stopping.**

Regenerative Brake

Short terminals RB1 and RB2 to regeneratively brake the motor to zero speed. The regenerative brake circuitry follows the FWD ACC and REV ACC trim pots. Open terminals RB1 and RB2 to accelerate the motor to set speed. **Do not use the regenerative braking for emergency stopping.**

Enable (Inhibit-Run)


Short pins 1 and 2 on terminal S0502 to coast the motor to zero speed. Short pins 2 and 3 on terminal S0502 to accelerate the motor to set speed. If no Enable switch is desired, jumper pins 2 and 3 on S0502 (factory default). ACE offers an accessory plug harness for connecting to the enable terminals; part number KTW-0004 [18 in (46 cm) leads]. **Do not use the enable for emergency stopping.**

Tachogenerator

Using tachogenerator feedback improves speed regulation from approximately 1% of motor base speed to 0.1% of motor base speed. Use tachogenerators rated from 7 VDC per 1000 RPM to 50 VDC per 1000 RPM. Connect the tachogenerator to terminals T1 (positive) and T2 (negative).

+15 and -15

RGA series drive can supply a regulated +15 and -15 VDC voltage (each sourcing 15 mA maximum) with respect to RB1 or T1 to isolated, external devices.



Installation

Mounting

- Drive components are sensitive to electrostatic discharge. Avoid direct contact with the circuit board. Hold the drive by the chassis only.
- Protect the drive from dirt, moisture, and accidental contact.
- Provide sufficient room for access to the terminal block and calibration trim pots.
- Mount the drive away from heat sources. Operate the drive within the specified ambient operating temperature range.
- Prevent loose connections by avoiding excessive vibration of the drive.
- Mount the drive with its board in either a horizontal or vertical plane. Six 0.19" (5 mm) wide slots in the chassis accept #8 pan head screws. Fasten either the large base or the narrow flange of the chassis to the subplate.
- The chassis should be earth grounded. Use a star washer beneath the head of at least one of the mounting screws to penetrate the anodized chassis surface and to reach bare metal.

Heat Sinking

The RGA400-10 requires an additional heat sink when the continuous armature current is above 5 amps. Use ACE heat sink kit part number HSK-0004. Use a thermally conductive heat sink compound (such as Dow Corning 340® Heat Sink Compound) between the chassis and the heat sink surface for optimal heat transfer.

Wiring

Use 18 - 24 AWG wire for logic wiring.

Use 14 - 16 AWG wire for AC line (L1, L2 115V, L2 230V) and motor (A1, A2, F1, F2) wiring.

Shielding Guidelines

As a general rule, ACE recommends shielding of all conductors. If it is not practical to shield power conductors, ACE recommends shielding all logic-level leads. If shielding of logic-level leads is not practical, the user should twist all logic leads with themselves to minimize induced noise. Refer to the user's manual for details on earth grounding shielded wires and filtering.

Fusing

RGA403 series drives provide on board fusing for the AC line (L1, L2 (230)). Fuses are fast acting fuses. RGA403-3 models contain fuses rated for 8A at 250 VAC. RGA403-10 models contain fuses rated for 20A at 250 VAC.

Startup

SELECT SWITCHES

Input Voltage Select (SW501, SW502)

Set the voltage switches SW501 and SW502 to either 115 or 230 to match the AC line voltage.

Armature Voltage Select (SW503)


Set the voltage switch SW502 to either 90 or 180 to match the maximum armature voltage.

Feedback Select (SW504)

Set the feedback select switch SW504 to either ARM for armature feedback or TACH for tachogenerator feedback.

Signal Select (SW505)

Set the signal select switch SW505 to the corresponding input signal. See the table in the Operation section for settings.



STARTUP


- Verify that no foreign conductive material is present on the printed circuit board.
- Ensure that all switches are properly set.

1. Turn the speed adjust potentiometer full counterclockwise (CCW) or set the analog input voltage or current signal to minimum.
2. Apply AC line voltage.
3. Enable the drive if using an enable switch on SO502. Otherwise, make sure the jumper is in place.
4. Slowly advance the speed adjust potentiometer clockwise (CW) or increase the analog input voltage or current signal. The motor slowly accelerates as the potentiometer is turned CW or as the analog input voltage or current signal is increased. Continue until the desired speed is reached.
5. Remove AC line voltage from the drive to coast the motor to a stop.

Copyright 2011 by American Control Electronics® - All rights reserved. No part of this document may be reproduced or retransmitted in any form without written permission from American Control Electronics®. The information and technical data in this document are subject to change without notice. American Control Electronics® makes no warranty of any kind with respect to this material, including, but not limited to, the implied warranties of its merchantability and fitness for a given purpose. American Control Electronics® assumes no responsibility for any errors that may appear in this document and makes no commitment to update or to keep current the information in this document.

Operation

Potentiometer Wiring



Unidirectional Forward

Unidirectional Reverse

Bidirectional

SW505 ANALOG INPUT DIP SWITCH SETTINGS

Input Signal Level	DIP SWITCH SETTING		
	1	2	3
Voltage	OFF	OFF	OFF
1-5 mA	ON	OFF	OFF
4-20 mA	OFF	ON	OFF
10-50 mA	OFF	OFF	ON

TOP BOARD TRIM POTS

Minimum Speed (MIN OUT): The MIN OUT setting determines the minimum motor speed when the speed adjust potentiometer or input voltage or current signal is set for minimum speed. See the calibration steps below to calibrate the MIN OUT.

Maximum Speed (MAX OUT): The MAX OUT setting determines the maximum motor speed when the speed adjust potentiometer or input voltage or current signal is set for maximum speed. See the calibration steps below to calibrate the MAX OUT.

Signal Input Adjust (SIGNAL INPUT ADJ): The SIGNAL INPUT ADJ setting adjusts out any motor drift. See the calibration steps below to calibrate the SIGNAL INPUT ADJ.

INPUT VOLTAGE SIGNAL CALIBRATION

Use a voltmeter and ammeter for voltage and current measurements, respectively. The following voltages and currents should be known.

I_{min} = Minimum input signal (between COM and INPUT 1 or INPUT 2)

I_{max} = Maximum input signal

O_{min} = Minimum output signal

O_{max} = Maximum output signal

- Step 1. Set the SW501 DIP switches appropriately. See the diagram in the Operation section for settings.
- Step 2. Connect the input signal common (-) to COM (terminal 7). If using a current input signal or a voltage input signal less than 0 to ± 25 VDC, connect the input signal reference (+) to INPUT 1 (terminal 8). If using a voltage input signal greater than 0 to ± 25 VDC, connect the input signal reference (+) to INPUT 2 (terminal 9).
- Step 3. Set the bottom board MIN SPD trim pot top full CCW and the MAX SPD trim pot to full CW.
- Step 4. Apply AC line voltage and the input signal.
- Step 5. Set the input signal to I_{min} .
- Step 6. Adjust the MIN OUT trim pot (P503) on the top board so that the output voltage measured between terminals OUT 1 (terminal 1) and OUT 2 (terminal 2) is O_{min} .
- Step 7. Set the input signal to I_{max} .
- Step 8. Calculate the test point voltage, V_{tp} :

$$V_{tp} = \frac{I_{max}}{2} \left(\frac{O_{max} - O_{min}}{I_{max} - I_{min}} \right)$$
- Step 9. Adjust the SIGNAL INPUT ADJ trim pot (P501) so that the voltage between COM (terminal 7) and TP (terminal 10) is V_{tp} .
- Step 10. Adjust the MAX OUT trim pot (P502) on the top board so that the output voltage measured between terminals OUT 1 (terminal 1) and OUT 2 (terminal 2) is O_{max} .
- Step 11. Repeat steps 4, 5, 6, 7, 9, and 10 using the same values already calculated.

Calibration

BOTTOM BOARD TRIM POTS

Minimum Speed (MIN SPD): Set the MIN SPD trim pot to full CW. Calibrate the minimum speed with the MIN OUT trim pot on the top board.

Maximum Speed (MAX SPD): Set the MAX SPD trim pot to full CW. Calibrate the maximum speed with the MAX OUT trim pot on the top board.

Forward Torque (FWD TQ) and Reverse Torque (REV TQ): The FWD TQ and REV TQ settings determine the maximum torque for accelerating and driving the motor in the forward and reverse direction.

To calibrate the FWD TQ:

1. With the power disconnected from the drive, connect a DC ammeter in series with the armature.
2. Set the FWD TQ trim pot to minimum (full CCW).
3. Set the speed adjust potentiometer to maximum forward speed (full CW).
4. Carefully lock the motor armature. Be sure that the motor is firmly mounted.
5. Apply line power. The motor should be stopped.
6. Slowly adjust the FWD TQ trim pot CW until the armature current is 150% of motor rated armature current.
7. Turn the speed adjust potentiometer to minimum speed (full CCW).
8. Remove line power.
9. Remove the stall from the motor.
10. Remove the ammeter in series with the motor armature if it is no longer needed.

To calibrate the REV TQ:

1. Follow the steps for calibrating the forward torque using the REV TQ trim pot and with the motor set to run in the reverse direction.

IR Compensation (IR COMP): The IR COMP setting determines the degree to which motor speed is held constant as the motor load changes. To calibrate the IR COMP:

1. Set the IR COMP trim pot full CCW.
2. Increase the speed adjust potentiometer until the motor runs at midspeed without load. A handheld tachometer may be used to measure motor speed.
3. Load the motor armature to its full load armature current rating. The motor should slow down.
4. While keeping the load on the motor, rotate the IR COMP trim pot until the motor runs at the speed measured in step 2. If the motor oscillates (overcompensation), the IR COMP trim pot may be set too high (CW). Turn the IR COMP trim pot CCW to stabilize the motor.
5. Unload the motor.

Forward Acceleration (FWD ACC): The FWD ACC setting determines the time the motor takes to ramp to a higher speed in the forward direction or to a lower speed in the reverse direction. To calibrate the FWD ACC, turn the FWD ACC trim pot CW to increase the forward acceleration time, and CCW to decrease the forward acceleration time.

Reverse Acceleration (REV ACC): The REV ACC setting determines the time the motor takes to ramp to a higher speed in the reverse direction or to a lower speed in the forward direction. To calibrate the REV ACC, turn the REV ACC trim pot CW to increase the reverse acceleration time, and CCW to decrease the reverse acceleration time.

Tachogenerator Feedback (TACH): The TACH setting, like IR COMP setting, determines the degree to which motor speed is held constant as the motor load changes. To calibrate the TACH trim pot:

1. Connect the tachogenerator to T1 and T2. The polarity is positive (+) for T1 and negative (-) for T2 when the motor is running in the forward direction.
2. Set the feedback select switch SW504 to ARM for armature feedback.
3. Set the speed adjust potentiometer or input voltage or current signal to maximum speed. Measure the armature voltage across A1 and A2 using a voltmeter.
4. Set the speed adjust potentiometer or input voltage or current signal to zero speed.
5. Set SW504 to TACH for tachogenerator feedback.
6. Set the IR COMP trim pot to full CCW.
7. Set the TACH trim pot to full CW.
8. Set the speed adjust potentiometer or input voltage or current signal to maximum speed.
9. Adjust the TACH trim pot until the armature voltage is the same value as the voltage measured in step 3.

Check that the TACH is properly calibrated. The motor should run at the same set speed when SW504 is set to either ARM or TACH.

Deadband (DB): The deadband trim pot determines the time that will elapse between the application of current in one direction before current is applied in the opposite direction. The deadband trim pot affects the resistance that a motor has to changes in shaft position at zero speed. Deadband is factory calibrated to approximately the 3 o'clock position for 60 Hz AC line operation. Recalibrate the deadband to the 9 o'clock position for 50 Hz operation. If you hear motor noise (humming), the deadband might be set too high. Turn the deadband trim pot CCW until the motor noise ceases.