Autonics DIGITAL PRESSURE SENSOR **PSA/PSB SERIES**

INSTRUCTION MANUAL



Thank you for choosing our Autonics product. Please read the following safety considerations before use

Safety Considerations

se observe all safety considerations for safe and proper product operation to avoid hazards lepha symbol represents caution due to special circumstances in which hazards may occur.

Warning Failure to follow these instructions may result in serious injury or death.

▲ Caution Failure to follow these instructions may result in personal injury or product damage

▲ Warning

- 1. Fail-safe device must be installed when using the unit with machinery that may cause serious injury or substantial economic loss. (e.g. nuclear power control, medical equipment, ships, vehicles, railways, aircraft, combustion apparatus, safety equipment, crime/disaster prevention devices, etc.) Failure to follow this instruction may result in personal injury, economic loss or fire.

 2. Do not use the unit in the place where flammable/explosive/corrosive gas, high humidity, direct sunlight, radiant heat, vibration, impact, or salinity may be present. Failure to follow this instruction may result in explosion or fire.

 3. Install on a device panel or to a pressure port directrify to use. Failure to follow this instruction may result in fire.

 4. Do not connect, repair, or inspect the unit while connected to a power source.

- Failure to follow this instruction may result in fire.

 4. Do not connect, repair, or inspect the unit while connected to a power source. Failure to follow this instruction may result in fire.

 5. Check 'Connections' before wiring.
 Failure to follow this instruction may result in fire.


 6. Do not disassemble or modify the unit.
 Failure to follow this instruction may result in fire.

⚠ Caution


- I. Use the unit within the rated specifications.
 Failure to follow this instruction may result in fire or product damage.
 2. Use dry cloth to clean the unit, and do not use water or organic solvent.
 Failure to follow this instruction may result in fire.
 3. This product is designed to detect the pressure of noncorrosive gas. Do not use for corrosive gas. Failure to follow this instruction may result in product damage.
- Failure to follow this instruction may result in product damage.

 A Keep metal chip, dust, and wire residue from flowing into the unit. Failure to follow this instruction may result in fire or product damage.

Dimensions OPSA Series Ø4, 2m 10.5 XA: Rc1/8 (standard), NPT1/8 (option) Bracket A Panel cut-out (panel thickness 0.8 to 3.5mm)









∆Caution



The tightening torque of one touch fitting should be Max. 10N·m.
It may cause mechanical trouble.

PSA Series has 2 kinds of brackets so it is able to install it in two different ways.

to install it in two different ways.

7. At first, please unscrew hexagon wrench bolt an assemble the bracket on this unit by fixing the hexagon wrench bolt.


In this case, tightening torque of hexagon wrench should be max. 3N·m. It may cause mechanical trouble.



Installation


I When installing pressure port it is able to bring pressure from 3 directions by changing the mounting direction of the pressure port.

2. Standard pressure port is Rc1/8 and option pressure port is NPT1/8. Use a general one-touch fitting.




prevent pressure leak.


4. Please block another two pressure ports not used with port plug.




Please connect it by using spanner(13mm) at the metal part in order not to overload on the body when connecting one touch fitting.





3. Please connect it by using spanner(10mm)



. It is able to use it without the pro-according to environment. In this case O-Ring between pressure port and its body should not be taken out in 2. It is able to use it without the pressure port







*Do not pull the cable with a tensile strength of 30N or over.
*The above specifications are subject to change and some models may be discontinued without notice
*Be sure to follow cautions written in the instruction manual and the technical descriptions


Specifications

Pressure type		Gauge pressure				
		Negative pressure type Standard pressure type		pe	Compound pressure type	
	NPN open collector output	PSA-V01- PSB-V01- PSB-V01C-	PSA-01- PSB-01- PSB-01C-	PSA-1- PSB-1- PSB-1C-	PSA-C01- PSB-C01- PSB-C01C-	
Model ^{**1}	PNP open collector output	PSA-V01P- PSB-V01P- PSB-V01P-	PSA-01P- PSB-01P- PSB-01CP-	PSA-1P- PSB-1P- PSB-1CP-	PSA-C01P- PSB-C01P- PSB-C01CP-	
Rated pressure range		0.0 to -101.3kPa	0.0 to 100.0kPa	0 to 1,000kPa	-100.0 to 100.0kPa	
Display pressure range		5.0 to -101.3kPa	-5.0 to 110.0kPa	-50 to 1,100kPa	-101.2 to 110.0kPa	
Max. pressure range		2 times of rated pressu	ire	1.5 times of rated pressure	2 times of rated pressure	
Applicable fluid		Air, Non-corrosive gas				
Power supply		12-24VDC ±10%(Ripple P-P: max. 10%)				
Current consumption		Max. 50mA				
Control output		NPN or PNP open collector output Load voltage: Max. 30VDC Load current: Max. 100mA Load current: Max. 100mA PNP: Max. 2VDC				
Hys	teresis ^{×2}	1digit fixed(2digits for p	osi unit)		2digits fixed	
Rep	eat error	±0.2% F.S. ±1digit			±0.2% F.S.±2digits	
Res	ponse time	Selectable 2.5ms, 5ms, 100ms, 500ms				
Short circuit protection Built-in						
Analog output		Output voltage: 1-5VDC ±2% F.S. Zero point: Within 1VDC ±2% F.S. Sesolution: Approx. 1/20 Sesol				
Display digit		3½ digit LED				
Display method		7 Segment LED				
Min. display interval		1digit(psi unit: 2 digits are fixed)		2digits		
Pressure unit		kPa, kgf/cm²,bar, psi, mmHg, mmH₂O, inHg		kPa, kgf/cm², bar, psi, mmHg, mmH ₂ O, inHg		
Display accuracy		0 to 50°C: Max. ±1% F.S., -10 to 0°C: Max. ±2% F.S.				
Vibration		1.5mm amplitude at frequency of 10 to 55Hz in each of X, Y, Z directions for 2 hours				
Environ /	Ambient temperature	-10 to 50, Storage: -20	to 60°C			
-ment	Ambient humidity	35 to 85%RH, Storage: 35 to 85%RH				
Material		PSA - Case: PC, Pressure port: die-cast (Zn) PSB - Case, Pressure port, Cover: IXEF PSB-C - Case, Pressure port, Cover: IXEF				
Protection		IP40(IEC standard)				
Cable	Cable type	Ø4mm, 5-wire, Length: 2m(AWG 24, core diameter: 0.08mm, number of cores: 40, insulation diameter: Ø1mm)				
	Connector type	5-wire, Length: 3m(AV)				
Weight ^{※3}				60g(approx. 70g), PSB-C : A	Approx. 160g (approx. 70g)	
		PSA standard: Rc1/8, P	SA ontion: NPT1/8 PS	B etandard: M5		

sis output mode, detection difference is variable

※2: In hysteresis output mode, detection difference is variable.
%3: The weight is with packaging and the weight in parentheses is only unit weight.
※F.S.: Rated pressure.
※There may be ± Idigit error in hysteresis by pressure unit calculation error.
%The specification of pressure port for PSA Series is marked on the upper part of the case.
%For using mmH₂O unit, multiply display value by 100.
%Environment resistance is rated at no freezing or condensation.

Input/Output Circuit and Connection Diagram



Unit Descriptions



Displays sensing pressure, every setting value and display error

2. 1 output Indicator(red): Output 1 is ON, LED will be ON

3. 2 output Indicator(FSA red, PSB green): Output 2 is ON, LED will be ON

4. Mode key: Enter to parameter or preset setting mode, and save setting value

Up key: Sets the setting value to upper step in preset setting or pressure unit, output mode, response time, analog output scale, key lock, peak hold value, bottom hold value display in parameter setting

6. Down key
Sets setting value to lower step in preset setting or pressure unit,
output mode, response time, analog output scale, key lock, peak hold,
bottom hold display in parameter setting.
7. Range of rating pressure: it is possible to change the pressure unit in
pressure sensor. Please use different unit label for your application.

Pressure unit change
PS□-V01(C)(P) and PS□-C01(C)(P) has 7 kinds of pressure unit and PS□-01(C)(P) and PS□-1(C)(P)
has 4 kinds of pressure unit. Please select the proper unit for application.
-PS□-V01(C)(P), PS□-1(C)(P): kPa, kgf/cm², bar, psi, mmHg, inHg, mmH₂O
-PS□-01(C)(P), PS□-1(C)(P): kPa, kgf/cm², bar, psi
When using mmH₂O unit, multiply display value by 100.

Output mode change
There are 6 kinds of control output mode in order to provide the various detection.
Select a mode for your proper application.
- Hysteresis mode[F 1]: When variable hysteresis is required for pressure detection.
- Automatic sensitivity setting mode[F 2]: When it is required to set detecting sensitivity automatically at proper position.
- Independent 2 output mode[F 3], F 4, F 5]: When it is required to detect pressure from two positions with one product.

Window comparison output mode[F= 6]: When it is required to detect pressure in a certain area.

Response time change (chattering prevention)
It can prevent chattering of control output by changing response time. t is able to set 4 kinds of response time (2.5, 5, 100, 500ms) and if the response time is getting longer, the sensing will be more stable by increasing the number of digital filter.

stable by increasing the number of digital filter.

Analog output scale setting
It is not fixed the analog output (1-5VDC) scale as the rated pressure range but this is a function to change properly for user's application. When the position [R I] for 1VDC output and the position [R 5] for 5VDC output are set, the pressure range of R I to R 5 is to 1-5VDC analog output.

This unit has 2 kinds of key lock function in order to prevent wrong operation.

*LoC: All keys are locked, it is impossible to change any parameter setting/preset, zero point adjustment, peak hold and bottom hold. (enables to change ⊨E ≡ mode only)

*PR.L: t is impossible to change parameter setting/preset, zero point adjustment. (Enables to change ⊨E ≡ mode)

*UnL: All of the setting is available, all keys are unlocked.

*Zero point adjustment
This function is to set the display value of pressure at zero when port is opened to atmospheric pressure.

Zero point adjustment affects analog output voltage.

*Peak hold and bottom hold, and to change □E ≡ mode)

*Peak hold and bottom hold function
This function is to diagnosis malfunction of the system caused by parasitic pressure or to check through memorizing the max/min, pressure that occurred in the system.


■ Output Operation Mode

XPSA/PSB Series has 6 kinds of output operation mode, please use proper output operation mode in accordance with sensing.

• Hysteresis mode[F 1] It can be set for pressure sensing level [5£1] and sensing differences [5£2]. OUT1 ON OUT2 OFF


• Independent 2 output mode[F 3, F 4, F 5] ①5Ł / and 5Ł 2 can be set independently within display pressure range. One is for control, the other is for alarm or optional control.

②The sensing hysteresis is fixed in 1digit.
(2 digits for psi unit and compound type)




Automatic sensitivity setting mode[F 2]
This function is to set pressure sensing level to the proper position automatically. It is set by received pressure from two positions[5£ 1,5£2].
The sensing hysteresis is fixed in 1digit. (2 digits for psi unit and compound type)
The pressure sensing level [5££] is shown in the following calculation.

 $5EE = \frac{(5EI + 5E2)}{2}$



• Window comparison output mode[F 5]
①It is able to set High-limit value[H:], Low limit
value[L: _0] of pressure sensing level in this mode.
②The sensing hysteresis is fixed to 1 digit (2 digits for psi unit and compound type)



ı	■ Error				
l	Error display	Description	Countermeasures		
l	Erl	If external pressure applied, when adjusting Zero point	Please try again after external pressure removing		
	Er2	When overloaded on control output	Remove overload		
	Er3	When the setting condition is not matched at automatic sensitivity setting mode	Set proper setting value after checking setting condition		
	ннн	When the applied pressure exceeds the upper display pressure range up	Apply pressure within display pressure		
	LLL	When the applied pressure exceeds the lower display pressure range down	range		
		•	·		

Accessory

OPSA/PSB (pressure unit label)


Only for PSA Series • Port plug Bracket A







Setting



In state of atmospheric pressure during RUN mode, press ▼ key and ▲ key at the same time for over

1sec.
2. When the zero point adjustment is completed, it will display 0.0 and return to RUN mode automatically. Wilf executing zero point adjustment when external pressure has been applied, £ will be flashing. Please execute zero point again in state of atmospheric pressure.

XPlease execute zero point adjustment regularly.

Parameter setting.

Parameter setting

 Set to pressure display unit, output operation mode, response time(chattering prevention), analog output scales or key lock. Please set parameter after unlocking key lock function when key lock function is set

(please see below key lock setting) RUN mode ♣ Press M key over 3 sec

Display unit [Unb]

Press A or key to select the unit

PR + W + Y 9F + W + BR - W + PS + W + AA + W + AH + W + HZO + W

((Pa) (kgt/cm²) (bar) (psi) (Press (M) key momentarily, the unit will be saved, then #For using mmH₂O unit, multiply display value by 100.

Output operation mode [oUt] ● UE and previous output operation mode will flas by turning on.(0.5sec.) Select the output operation mode with (A), (V) key F-1-0-F-2-0-F-3-0-F-4-F-5-0-F-5-0-F-5

(Press Mkey momentarily, the response time will be saved, then move to the next mode.) **↓** M Response time [5Pd]

• 5P and the previous response time will flash by turning on.(0.5sec.) • Select the response time with 🔼 🔻 key. 2.5 W 5.0 W 00 W 500 W (Press M key momentarily, the response time will be

↓ M Analog output scale (1VDC) [8 1]

A and the previous pressure will flash by turning on.(0.5sec.)
 Set the pressure which will output 1VDC with ▲ ▼

 key.
 Set range: Min. value of rated pressure ≤ [R I] $\leq 90\%$ of rated pressure (Press $\boxed{\text{M}}$ key momentarily, the selected pressure is set as 1VDC scales, then move to the next mode.)

↓ M

Analog output scale (5VDC) [R 5] A 5 and the previous pressure will flash by turning on.(0.5sec.)

• Set the pressure which will output 5VDC by ▲, ▼

• Set range: [A 1]+10% of rated pressure ≤
[A 5]≤Max. value of rated pressure
(Press M key momentarily, the selected pressure is set

as 5VDC scales, then move to the next mode.)

Key lock [দ돈님] 모든말 and the previous key lock will flash by turning

Select key lock with ▲, ▼ key.

*Key lock functions

•L c: Disable to change preset value and paramete value (Enable to change PE 9 mode only)

*CRU Disable to change preset value and paramete value (Enable to change PE 9 mode only)

 PRL: Disable to change parameter setting/preset, zero point adjustment. (Enables to check peak hold and bottom hold, and to change PEY mode) U ⊥ : Enable to change preset value and parameter

value(Lock off) Returns to RUN mode

When advance to parameter setting mode and preset setting mode, it displays "Setting item" and "Previous setting value" by 0.5 sec. turn. This display will stop by setting value by 0.5 sec. turn. This display will stop by pressing ▼ or ▲ key(Display setting value), if any key is untouched for over 1 sec., it will display old value by 0.5sec, turn again.

return to RUN mode with memorizing on EEPROM However, when there is any key is untouched for 60sec., it turns to RUN mode with keeping the previous setting value not current setting value.

*There is memory protection by EEPROM, but life cycle of EEPROM is 100,000 times.

of EEPROM is 100,000 times.

Peak hold and bottom hold check

1. Press *A key for over 3sec. in RUN mode.

2. *PEH and memorized max. pressure(Negative pressure type is for max. negative pressure) will flash by turning on (0.5sec.) then display peak hold value.

3. buH and memorized min. pressure(Negative pressure type is for min. negative pressure) will flash by turning on (0.5sec.) then display bottom hold value.

4. If pressing *A key one time shortly, memorized peak hold and bottom hold value will be removed then return to RUN mode.

*When the peak hold and bottom hold value is over the

OPreset value setting

 Set the pressure sensing level.
 Set preset value after unlocking key lock when key lock function is set. (please refer to the key lock setting)

3. Be sure that the setting method is different by each output operation mode

■ When hysteresis mode [F] and independent 2 output mode [F 3, F 4, F 5]

RUN mode **↓** M

and previous set sensing level 1 flash in 0.5se

by turns.
Set the pressure sensing level 1 by ▲ or ▼ key.

Set range: Min. display pressure < 5½

SMax. display pressure

Max. display pressure

(Press M key momentarily, sensing level 1 will be saved, then move to the next mode.)

↓ M

Pressure sensing level 2 •5₺2 and previous set sensing level 2 flash in 0.5se

by turns.

■ Set the pressure sensing level 2 by ▲ or ▼ key. • Set range: Hysteresis mode →
Min. display pressure ≤ 5£2 < 5£
Independent 2 output mode →

Min. display pressure < 5Ł∂ ≤
Max. display pressure
(Press M key momentarily, sensing level 2 will be saved, then move to the next mode.)

Returns to RUN mode

■ Automatic sensitivity setting mode [F 2]

RUN mode **↓** M Pressure sensing level 1

5b and previous set sensing level 1 flash in 0.5s by turns.
Apply the required pressure[5b] within the rated

pressure.

Press A key shortly one time, current sensitive set as sensing level 1.5£ and pressure is set as sensing level 1.5£ and the set sensing level 1 flash by turn (0.5sec.).
Set range: Min. display pressure < 5£ ≤ Max. display pressure-1%of rated pressure

Pressure sensing level 2

5 £ 2 and previous set sensing level 2 flash in 0.5sec Apply the required pressure[5 £ 2] within the rated

pressure.

Press key shortly one time, current sensing pressure is set as sensing level 2.5 ± 2 and the set sensing level1 flash by turn (0.5 sec.).

Set range:5 +1% of rated pressure ≤ 5 ≥ ≤Max. display pressure ※If differences of between 5₺ and sensing level are not enough, ₺ 3 flashes 3 times then retruns to 5 £ 2 setting. Please re-execute the setting for the

※It is possible to set repeatedly by

▲ key, the las: setting is set as the sensing level 2

utomatic sensitivity and fine adjustment

5 £ 2 and sensing level [5 £ £] flash in 0.5sec. by to

1 M

Returns to RUN mode

When checking the value of sensing level 1, 2 [5£ 5£2] and automatic sensitivity setting value[5££], press M key shortly and continuously.

Example of the setting in automatic sensitivity setting mode (to check absorption of component by vacuum pressure): The state of removed target is 5£ and the state of absorbing target is 5£2. By A key, sensing level [5£2] value is set in the between 5£ and 5£2 automatically.

■ Window comparison output mode [F 5]

RUN mode

Pressure sensing level 1 and previous set sensing level 1 flash in 0.5sed • Set the pressure sensing level 1 by ▲ or ▼ key

• Set range: Min. display pressure ≤ L <
Max. display pressure
(Press M key momentarily, sensing level 1 will be saved, then move to the next mode.)

Pressure detecting level 2

HI and previous set sensing level 1 flash in 0.5se turns.
Set the pressure sensing level 2 by ▲ or ▼ key.

Set range: L < H | S Max. display pressure (Press M key momentarily, sensing level 1 will be saved, then move to RUN mode.) **↓** M

Returns to RUN mode

Cautions during Use

1. Follow instructions in 'Cautions during Use'.

Otherwise. It may cause unexpected accidents. 2. 12-24VDC power supply should be insulated and limited voltage/current or Class 2, SELV power supply device.

3. Use the product, 3 sec after supplying power. 4. When using switching mode power supply, frame ground (F.G.) terminal of power supply should be grounded.

5. Wire as short as possible and keep away from high voltage lines or power lines, to prevent

inductive noise. 6. This unit may be used in the following environments.

(1) Indoors (in the environment condition rated in 'Specifications') ②Altitude max. 2,000m

®Pollution degree 2 4 Installation category III

Main Products

■ Door Sensors ■ Door Side Sensors ■ Area Sensors

■ Fiber Optic Sensors

- Counters ■ Timers
- Proximity Sensors ■ Panel Meters
- Rotary Encoders ■ Display Units ■ Connector/Sockets ■ Sensor Controllers
- Graphic/Logic Panels ■ I/O Terminal Blocks & Cables ■ Field Network Devices ■ Stepper Motors/Drivers/Motion Controllers ■ Control Switches/Lamps/Buzzers

■ Temperature/Humidity Transc

■ SSR/Power Controllers

■ Switching Mode Power Supplies ■ Laser Marking System(Fiber, CO₂, Nd:YAG)

DRW171187AB

Pressure sensing level 1