Autonics

GEARED TYPE 5 PHASE STEPPER MOTOR

INSTRUCTION MANUAL







[Frame size 42mm] [Frame size 60mm]

[Frame size 85mm]

Thank you for choosing our Autonics product. Please read the following safety considerations before use.

Safety Considerations

**Please observe all safety considerations for safe and proper product operation to avoid hazards

※▲ symbol represents caution due to special circumstances in which hazards may occur.

▲ Warning Failure to follow these instructions may result in serious injury or death. ⚠ Caution Failure to follow these instructions may result in personal injury or product damage.

1. Fail-safe device must be installed when using the unit with machinery that may cause serious injury or substantial economic loss. (e.g. nuclear power control medical equipment, ships, vehicles, railways, aircraft, combustion apparatus, safety equipment, crime/disaster prevention devices, etc.)

Failure to follow this instruction may result in fire, personal injury, or economic loss. 2. Fix the unit on the metal plate.

Failure to follow this instruction may result in personal injury, or product and ambient equipment damage.

3. Do not connect, repair, or inspect the unit while connected to a power source. Failure to follow this instruction may result in fire.

4. Install the unit after considering counter plan against power failure. Failure to follow this instruction may result in personal injury, or economic loss.

5. Check 'Connections' before wiring.

Failure to follow this instruction may result in fire.

6. Do not disassemble or modify the unit.

Failure to follow this instruction may result in electric shock or fire.

7. Install the motor in the housing or ground it.

Failure to follow this instruction may result in electronic shock, fire, or personal injury. 8. Make sure to install covers on motor rotating components.

Failure to follow this instruction may result in personal injury.

9. Do not touch the unit during or after operation for a while Failure to follow this instruction may result in burn due to high temperature of the surface.

10. Turn OFF the power directly when error occurs.

Failure to follow this instruction may result in electric shock, fire, or personal injury.

⚠ Caution

1. Use the unit within the rated specifications.

Failure to follow this instruction may result in fire or product damage.


2. Use dry cloth to clean the unit, and do not use water or organic solvent. Failure to follow this instruction may result in fire.

3. Do not use the unit in the place where flammable/explosive/corrosive gas, humidity, direct sunlight, radiant heat, vibration, impact, or salinity may be present. Failure to follow this instruction may result in fire or explosion.

4. The motor may overheat depending on the environment.

Install the unit at the well-ventilated environment and forced cooling with a cooling fan. Failure to follow this instruction may result in product damage and degrada ion.

Ordering Information



% The above specifications are subject to change and some models may be discontinued without notice. % Be sure to follow cautions written in the instruction manual and the technical descriptions

Specifications

Frame size 42mm					
Model	A10K-S545(W)-G5	A15K-S545(W)-G7.2	A15K-S545(W)-G10		
Max. holding torque*1	10 kgf cm (1.0 N·m)	1.5 kgf cm (1.5 N·m)	•		
Rotor moment of inertia**2	68 g·cm² (68x10 ⁻⁷ kg m	n ²)			
Rated current	0.75A/Phase				
Basic step angle	0.144 /0.072 (Full/Half step)	0.1 /0.05 (Full/Half step)	0.072 /0.036 (Full/Half step)		
Permissible speed range	0 to 360 rpm	0 to 250 rpm	0 to 180 rpm		
Backlash [min]	±35' (0.58°)		•		
Weight**3	Approx. 0.68kg (approx. 0.58kg)				

Frame size 60mm				
Model	A35K-M566(W)-G5	A40K-M566(W)-G7.2	A50K-M566(W)-G10	
Max. holding torque*1	35 kgf·cm (3.5 N·m)	40 kgf cm (4.0 N·m)	50 kgf-cm (5 0 N-m)	
Rotor moment of inertia ^{*2}	280 g·cm² (280x10 ⁻⁷ kg·m²)			
Rated current	1.4A/Phase			
Basic step angle	0.144 /0.072 (Full/Half step)	0.1 /0 05 (Full/Half step)	0.072 /0 036 (Full/Half step)	
Permissible speed range	0 to 360 rpm	0 to 250 rpm	0 to 180 rpm	
Backlash [min]	±20' (0.33')			
Weight**3	Approx. 1 57kg (approx. 1.3kg)			

Frame size 85mm						
Model	A140K- M599(W)-G5	A140K- G599(W)-G5	A200K- M599(W)-G7.2	A200K- G599(W)-G7.2	A200K- M599(W)-G10	A200K- G599(W)-G10
Max. holding torque ^{*1}	140 kgf-cm (14 N·m)		200 kgf-cm (20 N·m)			
Rotor moment of inertia*2	2,700 g cm ² (2,700x10 ⁻⁷ kg m ²)					
Rated current	1.4A/Phase	2.8A/Phase	1.4A/Phase	2.8A/Phase	1.4A/Phase	2.8A/Phase
Basic step angle	0.144 / 0.072 (Full/Half step)		0.1 / 0 05 (Full/Half step)		0.072 / 0 036 (Full/Half step)	
Permissible speed range	0 to 360 rpm		0 to 250 rpm		0 to 180 rpm	
Backlash [min]	±15' (0 25°)					
Weight**3	Approx. 4.88kg (approx. 4.4kg)					

X1: Max. holding torque is standard torque when supply the rated current and stop the motor for comparing the specifications of motors.


**2: Moment of rotor inertia indicates a part, except Gear Head part.

X3: The weight includes packaging. The weight in parenthesis is for unit only

O Comm	on specification	ons		
Operation type		Planetary Geared type		
Insulation class		B type (130℃)		
Insulation	n resistance	Over 100MΩ (at 500VDC megger) between motor coil-case		
Dielectric strength		1 kVAC (at 0.75 A/Phase is 0.5 kVAC) 50/60Hz for 1 min between motor coil case		
Tempera	ture rise	5-phase excitation for rated current, below 80°C at stopped (resistance method)		
	Ambient temp.	-10 to 50 °C, storage: -25 to 85 °C		
	Ambient humi.	35 to 85%RH, storage: 35 to 85%RH		
Stop ang	le error ^{×1}	±3' (±0.05)		
Shaft vib	ration ^{*2}	0.05mm T.I R.		
Radial movement ^{*3}		Max. 0.025mm (Load 5N)		
Axial movement*		Max. 0.075mm (Load 10N)		
Concentricity for shaft of setup in-low		0.075mm T.I.R.		
Perpendicularity of set- up plate shaft		0.075mm T.I.R.		
Protection structure		IP30 (IEC34-5 standard)		

X1: Specifications are for full-step angle, with no-load (values may vary by load size.) X2: T.I R (Total Indicator Reading) - The difference between the maximum and minimum readings of a

dial gauge during one complete revolution of monitored reference ◎ Ø0.075 A 7 0.05



X3: Amount of radial shaft displacement when adding a radial load (5N) to the tip of the motor shaft. *4: Amount of axial shaft displacement when adding a axial load (10N) to the shaft *Rotation direction of the Motor and the Gear Head output axis is same

Connection Diagram


Autonics 5-phase stepper motors use pentagon wiring methods.

Therefore, it is a proper product for the driver working as a bipolar pentagon driving method of 5 The wiring colors for each phase and lead-wire are as follows


Orange Green O-C Phase

Dimensions


O Frame size 42mm



O Frame size 60mm



O Frame size 85mm




Sectioned A-A Parallel key Sectioned B-B XThese dimensions are for dual shaft models. Single shaft models do not include shafts indicated in

Installation

1. Mounting direction

the dotted lines.

Motor can be mounted in any directions-facing up, facing down and side ways. No matter which direction motors to be mounted, be sure not to apply overhung or thrust load on the shaft. Refer to the table below for allowable shaft overhung load / thrust load.



W. The distance from the share in none (min)							
Motor size	The distance from the shaft in front (mm), Allowable overhung load [kgf (N)]					Allowable	
	D=0	D=5	D=10	D=15	D=20	thrust load	
Frame size 42mm	7 3 (73)	8.4 (84)	10 (100)	12.3 (123)	_	5 (50)	
Frame size 60mm	25 (250)	27 (270)	30 (300)	34 (340)	39 (390)	10 (100)	
Frame size 85mm	48 (480)	54 (540)	60 (600)	68 (680)	79 (790)	30 (300)	


Do not apply excessive force on motor cable when mounting motors Do not forcibly pull or insert the cable. t may cause poor connection or


In case of frequent cable movement required application, proper safety countermeasures must be ensured



With considering heat radiation and vibration isolation, mount the motor as tight as possible against a metal panel having high thermal conductivity such as iron or aluminum.

When mounting motors, use hexagon socket screws, spring washers and flat washers. Refer to the table below for allowable thickness of mounting plate and using bolt.






3. Connection with load

(Counter bore or Through hole)

When connecting the load, be sure of the center, tension of the belt, and parallel of the pulley. When connecting the load such as a pulley, a belt, be sure of the allowable thrust load, radial load,

and shock. Tighten the screw for a coupling or a pulley not to be unscrewed. If the center of the load is not matched to that of shaft, it may cause severe vibration, shaft damage or shortened life cycle of bearings.

When connecting a coupling or a pulley on the motor shaft, be sure of damage of the motor shaft and the motor shaft bearing. Do not disassemble or modify motor shaft to connect with the load. Please contact us if necessary.



XUse Autonics flexible coupling (ERB Series)

4. Installation condition

Install the motor in a place that meets certain conditions specified below.

It may cause product damage if instructions are not following.

①The inner housing installed indoor

(This unit is manufactured for attaching to equipment, Install a ventilation device.) ②Within -10 to 50 ℃ (at non-freezing status) of ambient temperature

(3) Within 35 to 85%RH (at non-dew status) of ambient humidity

The place without explosive, flammable and corrosive gas

The place without direct ray of light ©The place where dust or metal scrap is not entered into the unit

The place where water, oil, or other liquid are not touched ®The place where strong alkali or acidity does not exist closely

The place where easy heat dissipation could be made

@The place where no continuous vibration or severe shock

The place with less salt content

@The place with less electronic noise occurs by welding machine, motor, etc.

The place where no radioactive substances and magnetic fields exist.

t shall be no vacuum status as well.

Cautions during Use

I. Follow instruc ions in 'Cautions during Use'. Otherwise, It may cause unexpected accidents.

2. Using motors at low temperature may cause reducing ball bearing's grease and gear part consistency and friction torque is increased. Start the motor in a steady manner since motor's torque is not to be influenced.

3. Be careful of backlash when positioning the motors in bo h CW/CCW directions.

Geared type stepper motor use he high accuracy gear for positioning and it realizes low backlash. However, when positioning the motor in bo h CW/CCW directions, it may cause problem.

Therefore, make sure that motor positioning will be made in one single direction in case of geared type motors.

4. For using motor, it is recommended to maintenance and inspection regularly.

■ Temperature Controllers

SSRs/Power Controllers

■ Counters

■ Panel Meters

■ Display Units

■ Sensor Controllers

■ Temperature/Humidity Transducers

■ Tachometer/Pulse (Rate) Meters

①Unwinding bolts and connec ion parts for he unit installation and load connection ②Strange sound from ball bearing of the unit

⑤Inconsistency between the axis of motor output and the center, concentric (eccentric,

3 Damage and stress of lead cable of the unit (4) Connection error wi h driver

declination) of the load, etc. 5. This unit may be used in the following environments

①Indoors (in the environment condition rated in 'Specifications')

②Altitude max. 2.000m ③Pollution degree 2

(4) Installation category II

Major Products

■ Fiber Optic Sensors ■ Door Sensors

■ Door Side Sensors

■ Area Sensors

■ Proximity Sensors

Pressure Sensors

Connector/Sockets

■ Switching Mode Power Supplies

■ Control Switches/Lamps/Buzzers

■ I/O Terminal Blocks & Cables

■ Stepper Motors/Drivers/Motion Controllers

■ Graphic/Logic Panels

■ Field Network Devices ■ Laser Marking System (Fiber, CO₂, Nd: YAG)

■ Laser Welding/Cutting System

DRW161300AB