

ELITE INDUSTRIAL MANUFACTURING

SYSTEM WIRING FOR STANDARD PACKAGE CONNECTION

DO NOT USE T3 FOR CONTROL
VOLTAGES USE L1 AND L2 ONLY.

PHASE CONVERTERS MUST BE RUNNING
BEFORE CUSTOMER MACHINE CAN START

